

Police Station Montpelier, VT



City of Montpelier ADA Transition Plan

November 2018



Institute for Human Centered Design

200 Portland Street, Boston, MA 02114

www.IHCDesign.org • info@IHCDesign.org

617-695-1225 voice/tty

Police Station, Montpelier, VT

Background

Montpelier Police Station is located at 1 Pitkin Court, just east of the Montpelier Fire Station and City Hall, and abutting a parking lot that is used by visitors to all three buildings. Four parking spaces are associated specifically with the Police Station, including one car accessible space located near a ramp that provides access to the main entrance on the first floor.

The Police Station is a two story building. The building has an elevator, but public access is limited to the entry area lobby, a community training room, a single-user toilet room and two single-prisoner holding cells, all of which are located on the first floor.

Key Accessibility Issues

All of the accessibility issues at the Police Station are minor in nature.

Parking

Accessibility issues include lack of a van-accessible parking space and access aisles that have excessive running and cross slopes (5.5%).

Lobby

Accessibility issues include lack of an accessible service counter.

Public Toilet Room

Accessibility issues include a flush control that is not on the open or transfer side, and lack of a visible and audible alarm.

Detention Cells





Accessibility issues include lack of side and rear grab bars at the toilet in the detention cell with the required clear floor space (has water fountain).

Order of Magnitude Cost Estimates





- Miscellaneous corrective measures (van accessible parking space, grab bars at toilet in accessible cell, accessible counter in lobby, etc.): \$2,810

Total: \$2,810



**City of Montpelier
Montpelier Police**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
Approach and Entrance												
Off-Street Parking Lot or Garage												
1	Parking	Ext.		Off-Street Parking Lot or Garage	Visitor		Total # of parking Total # of designated accessible parking spaces Total # of designated van accessible spaces Running or cross slope at space > 1:50 (2.00%) Running or cross slope at access aisle > 1:50 (2.00%) Sign does not have the designation "Van Accessible"	4 1 - 5.5% 5.5% -	Re-stripe to provide a van accessible parking space and access aisle. Include sign with the phrase "Van Accessible" positioned 60" min. above the ground. Clear branches from existing sign with the International Symbol of Accessibility, reduce running and cross slope at space and access aisle to be no steeper than 1:50 (2.00%) in all directions.	1	438	\$438
Access to Goods and Services												
Means of Egress												
2	Across From Elevator Restricted Area	1		Means of Egress	N/A		Tactile exit sign not provided	-	Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above finish floor located on the latch side of the door.	2	116	\$232
3	Lobby	1		Means of Egress	N/A		Tactile exit sign not provided	-	Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above finish floor located on the latch side of the door.	1	116	\$116
Interior Access Route												
4	Outside Restricted Area	1		Interior Access Route	N/A		Obstructed by protruding objects	9"	Provide a cane detectable barrier.	1	153	\$153

**City of Montpelier
Montpelier Police**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
Signage												
5	Parking	Ext.		Signage	Designation		International Symbol of Acc. not compliant	-	International Symbol of Accessibility sign obstructed by tree branches. Trim branches to make sign visible.	1	100	\$100
Service Counter												
6	Lobby	1		Service Counter	N/A		Counter > 36" high	41"	Provide a counter that is 36" max. above the finish floor.	1	440	\$440
Detention Facilities												
7	Holding Cell	1		Detention Facilities	Other		< 3% of holding cells have mobility features	-	Provide a side wall grab bar that is 42" long min. located 12" max. from the rear wall. Provide a rear wall grab bar that is 42" long min. and extends from the toilet 12" min. on one side and 24" min. on the open side (transfer side). Mount grab bars 33" min. and 36" max. above the floor.	1	898	\$898
Benches												
8	Main Entrance	Ext.		Benches	N/A		No accessible route to 20% of benches	-	Relocate 20% of benches (at least 1) on an accessible route.	1	Labor	\$0
Toilet & Bathing Rooms												

**City of Montpelier
Montpelier Police**

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
Overall Access												
9	Toilet Room	1		Overall Access	Toilet Room		Audible and visible alarms not provided	-	When fire system is updated, ensure that a visible and audible fire alarm is installed.	1	346	\$346
Single-User Toilet												
10	Toilet Room	1		Single-User Toilet	N/A		Flush control not on open side	-	Relocate the flush control to the open side.	1	187	\$187